

APPENDIX C—Images of first-floor structural failure (images from Figures 2a and 2b)



Soft first floor garage, lacking shear strength, causes house to collapse during strong shaking. Image source: [U.S. Geological Survey](#)



Cripple wall lacking shear strength contributed to house collapse. Image source: [U.S. Geological Survey](#)